Contractor Name: Building Name Cooridor Unit (s)/Bldg 22 **LSE-1 Correction Calculator:** Ck'd By: WRT This Change Is Applied To Total Bldg # (s) =1 44 5/2/2020 Prepared by: LSE Inspector Units = Page: 1 LSE-A-XXX Drawing Type of Change EXAMPLE: Where? Located at Each Stair Well Entrance Inside sheet # view# dim changed deleted added Cooridors, I.E. 2 Per Cooridor Х Change ==> ADDED NOTE; CHASE IN KITCHEN; SEE DETAIL C1/A-501.1 **Materials Costs** Supervision Labor Direct Labor Fringe Labor Cost Item # Description Labor Hrs Hrly Rate MATERIALS AS LISTED 108.00 2 ELECTRICIAN Ś 45.90 Ś 21.21 \$ 67.11 Ś 67.11 1 3 \$ 4 5 \$ 6 SUPERVISION ---G & A Charge 108.00 67.11 1.00 Item Totals ==> \$ HI GETax 4.712% ==> 5.09 3.16 113.09 70.27 Totals ==> Total This Sheet # => \$ 183.36 For ONE Unit Sketch: 8.067.89 Total for All Affected Units **Detailed Description** QTY Materials \$ Unit TOTAL MAT Hrs Trade \$ \$ 1 98.00 EACH \$ EXIT LIGHT WITH EMERGENCY LED LIGHTS 98.00 \$ 4 2.50 EACH \$ MOUNTING FASTENERS 10.00 \$ TOTAL MATERIALS 108.00 NOTE: ADDITIONAL ELECTRICIAN WORK MAY BE REQUIRED DEPENDING UPON CONDITIONS 1 ELECTRICIAN \$ **ELECTRICIAN** 64.55 \$ SUPERVISE LAYOUT **SUPERVISOR** 1

| | Carpenter | Laborer 1 | Dry Waller | Painter | PLUMBER | ELECTRICIAN | SPECIALTY 1 | SPECIALTY 2 |
|---------------|-----------|-----------|------------|----------|----------|-------------|-------------|-------------|
| Rate / hr = | \$ 45.65 | \$ 35.35 | \$ 45.90 | \$ 36.35 | \$ 43.21 | \$ 46.85 | | |
| Fringe / hr = | \$ 21.21 | \$ 18.41 | \$ 21.21 | \$ 28.20 | \$ 21.21 | \$ 26.81 | | |